

Oil Field Environmental Incident Summary

Incident: 20150817150551 **Date/Time of Notice:** 08/17/2015 15:05

Responsible Party: Continental Resources, Inc.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: DOBS CTB

Field Name: CEDAR HILLS

Well File #:

Date Incident: 8/16/2015 **Time Incident:** 20:15 **Facility ID Number:** 413779-03

County: SLOPE **Twp:** 133 **Rng:** 106 **Sec:** 32 **Qtr:** SE SE

Location Description:

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

NA

Potential Environmental Impacts:

Gravel in dikes.

Action Taken or Planned:

Contaminated gravel was removed from dikes.

Wastes Disposal Location: Little Missouri Special

Agencies Involved:

Updates

Date: 8/17/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within the dikes. NDIC retains oversight.